EN ISO 20471, EN 343 Hi-Visibility Foul Weather Warning Coat



Code: CBJENG SY

Description: High Visibility Foul Weather Warning Coat.

Style Identification: Two bands around chest, 2 bands on each arm and 1 band over each shoulder.



3 EN ISO 20471 2013 Class 3 Area of High Visibility Yellow Background and Retro Reflective Tape



3

EN 343 2003 + A1 2007 Class 3 Water Penetration and Class 1 Water Vapour Resistance



These garments bear CE marking to demonstrate compliance with EC Directive EC/686/89 Personal Protective Equipment Annex II Health & Safety

Limitations of Use: This garment must always be worn correctly with the zip and storm flap fastened.

Keep Clean: To ensure optimum conspicuity this garment must be kept clean and regular comparisons are recommended against a new garment.

Disposal: Please dispose of the garment in a responsible, safe manner.

Code: CBJENG SY

Aftercare: For instructions on washing, see care label in garment. Company will not accept liability for garments where care labels have been ignored, neglected, defaced or removed.











Max. 25 x Wash Cycles

Do not wash in biological powder. Wash as synthetics. Machine Warm minimum wash. Cold rinse, short spin, do not wring.

The stated maximum number of cleaning cycles is not the only factor related to the lifetime of the garment.

The lifetime will also depend on usage, care, storage etc.

Storage & Transportation: Always store in clean, dry conditions. Do NOT store in places subject to direct, strong sunlight. This garment is suitable for transportation as supplied by the manufacturer.

Available Sizes and Selection

Designed with (20cm) over measure. A larger size may be required if worn over other clothing. Fit according to chest size:

Size:	Chest Size:	Height:
Small	86 - 94	164 - 172
Medium	94 - 102	172 - 180
Large	102 - 110	180 - 188
XLarge	110 - 118	188 - 196
XXL	118 - 129	196 - 204
XXXL	129 - 141	196 - 204

Wearing Time		
Temperature of working environment °C	1 R°tabove 40 min	
25	60	
20	75	
15	100	
10	240	
5	-	
"-" means: No limit for wearing time		





Non-Breathable Coated Polyester body with Reflective Tape

EN ISO 20471 2013 EN 343 2003 + A1 2007

High Visibility Warning Clothing





CBJENG SY

This garment must be kept clean to be effective. Replace if permanently stained or faded.











P.O. Box 13636,

West Bromwich, B70 1BQ